



Die bestimmungsgemäße Verwendung dieser Werkzeuge ist die Reparatur, Instandhaltung und Wartung. Prager & Co. KG übernimmt keine Haftung für eine unsachgemäße Verwendung dieser Werkzeuge. Prager & Co. KG kann nicht für Schäden an Personen, Gegenständen oder Geräten verantwortlich gemacht werden, die sich bei der Nutzung dieser Werkzeuge ergeben.



Nr. 36901 - Motoreinstell-Werkzeug-Satz, Hyundai / Kia

- für 1.1, 1.4, 1.5, 1.6 und 1.7L Common-Rail Diesel Motoren ab 2004
- im Hyundai Accent, Elantra, i20, i20 Active, i20 Coupe, ix20, i30, ix35, i40, Matrix und Tucson
- im Kia Carens, Cee'd, ProCee'd, Cerato, Optima, Picanto, Rio, Soul, Sportage und Venga
- zum Arretieren der Spanneinrichtung und der Kurbelwelle
- zur Demontage des Hochdruckpumpenrades
- beim Steuerkettenwechsel oder der Motorreparatur


für Motorcodes:

D3FA, D4FA, D4FAH, D4FAL, D4FB, D4FBH, D4FBL, D4FC, D4FD, D4FDH, D4FDL

OEM Vergleichsnummern:

092312B100, 092313N100, 093312A000, 093312A010

Nr.	Art. Nr.	Beschreibung	OEM Vergleichsnummer
1	36901-01	Hochdruckpumpenrad-Abzieher	093312A000, 093312A010
2	36901-02	Arretierdorn Kettenspanner (2 Stk.)	
3	6901	Schwungrad-Blockierwerkzeug	092312B100, 092313N100



- Motor nicht starten, wenn die Werkzeuge noch montiert sind.
- Die Blockierwerkzeuge dürfen nicht beim Lösen oder Festziehen von Kurbelwellen- oder Nockenwellen-Rädern zum Gegenhalten verwendet werden.
- Angegebene Daten erfolgen unter Vorbehalt.
- Diese Werkzeuge nur unter Beachtung aller Sicherheitshinweise, technischen Dokumentationen und Vorgaben des Fahrzeugherstellers verwenden.



The intended purpose of these tools is for repairing, servicing and maintaining. Prager & Co. KG does not accept any liability for incorrect use of any of these products. Prager & Co. KG cannot be held responsible for any damage to personnel, property or equipment when using these tools.



No. 36901 - Timing Tool Set, Hyundai / Kia

- for 1.1, 1.4, 1.5, 1.6 and 1.7L Common-Rail diesel engines from 2004 onwards
- in Hyundai Accent, Elantra, i20, i20 Active, i20 Coupe, ix20, i30, ix35, i40, Matrix and Tucson
- in Kia Carens, Cee'd, ProCee'd, Cerato, Optima, Picanto, Rio, Soul, Sportage and Venga
- for locking the tensioning devices and the crankshaft
- for dismantling the high-pressure pump sprocket
- for timing chain replacement or engine repair


for engine codes:

D3FA, D4FA, D4FAH, D4FAL, D4FB, D4FBH, D4FBL, D4FC, D4FD, D4FDH, D4FDL

OEM comparison numbers:

092312B100, 092313N100, 093312A000, 093312A010

No.	Item No.	Description	OEM Comparison Number
1	36901-01	High Pressure Pump Sprocket Puller	093312A000, 093312A010
2	36901-02	Tensioner Locking Pin (2 pcs.)	
3	6901	Flywheel Locking Tool	092312B100, 092313N100



- Remove all tools before starting engine.
- Do not use the locking tools as counterholder when loosening or tightening camshaft or crankshaft sprockets.
- No responsibility is taken for the correctness of this data.
- Always observe and follow all safety notes, technical documentations, specifications and instructions of the vehicle manufacturer.